

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Drawer 21-
Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐

2. NAME OF OPERATOR

J.M. Huber Corporation

3. ADDRESS OF OPERATOR

1900 Wilco Bldg., Midland, Texas 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2310' ESL & 990' FEL of Sec. 12
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☒
☒
☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/2/85 Perforate Delaware Pay 2982'-92' and 2950'-60' w/40 (0.50" dia.) shots.
7/3/85 Acidize perms w/2100 gals. 7 1/2% NeFe HCL acid.
7/4/85 Fractured perforations 2982-60' (OA) w/35,000 gals. gelled wtr containing 52,500# 20-40 sand & 25,000# 12-20 sand.
7/6-12/85 Swab test well
7/12-24/85 Set pumping unit and build tank battery.
7/25/85 Start pumping unit and testing well.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert R. Glenn

TITLE Dist. Prod. Mgr. DATE July 26, 1985

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD TITLE
CONDITIONS OF APPROVAL, IF ANY:

DATE

JUL 30 1985

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO