

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-57633

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

J.C. Williamson

3. ADDRESS OF OPERATOR

P.O. Box 16 Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1980' FSL & 440' FWL

FEB 1 '89

14. PERMIT NO.

30-015-25994

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3288.2' GR

O. C. D.
ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Exx Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat Delaware

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Sec. 15-20-29

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

REPAIRING WELL

☐
☐
☐
☐

SHOOTING OR ACIDIZING

ALTERING CASING

(Other) Continued drlg operations

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-01-88

to

12-15-88

Moved in cable tool, working days, found hole filled up to 2167' with caved reef rock, caved reef rock, cleaned out down to top of fish @ 2175' and drill around fish 6.9" - 2' 2" of shoe and bailer and 4' 7" of 2-7/8" tbg. Pull out for new bit. Hole caved back to top of bit, began drilling here, got down beside of bit and began pounding on shoe and bailer, made no progress for several days and moved off on 12-15-88.

12-31-88

Moved in Pulling unit and reverse circulating unit, power swivel and rig up same.

01-01-89

Picked up 7-7/8" used bit, 6 - 4" drill collars, 2-7/8" tbg. GIH and attempt to drill past junk (junk - 6' 4" of 2-7/8" tbg., bailer shoe and notched collar) drill on top of and 4' past junk, continued trying to make progress till we had to trip bit.

01-02-89

Attempt to drill w/new bit, felt we were destroying bit, COOH and WOO.

*see attached reports for continued drlg operations and schematic of hole.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production

DATE 01-13-89

(This space for Federal or State office use)

APPROVED BY

TITLE

ACCEPTED FOR RECORD

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 30 1989

536

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO