

12. OTHER INFORMATION

- A. Topography: The land surface has about 2° slope. The ground level elevation of the well site is 3987.8'.
- B. Soil: The soil consists of silt loams, silty clay loams and clay loams underlain by caliche.
- C. Ponds and streams: There are no rivers, streams, lakes or ponds in the area.
- D. Archaeological survey: An Archaeological survey was conducted on March 17, 1989. This clearance report is in the BLM files for this Re-entry.

13. FIELD REPRESENTATIVE

The following is the field representative responsible for assuring compliance with the approved surface use and operations plan:

Petroleum Engineer

A. B. "Tony" Sam
(915) 684-4561
(915) 685-1215

CERTIFICATION:

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drill site and access route; that I am familiar with the conditions which currently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and that the work associated with operations proposed herein will be performed by Sendero Petroleum Inc. and its contractors and subcontractors in conformity with this plan and the terms and conditions under which it is approved. This statement is subject to the provisions of 18 U.S.C. 1001 for the filing of a false statement.

5-10-90

Date

AB Sam

A. B. Sam, President