

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

SEP 07 '90

WELL API NO. 30-015-26156
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Airport West AGL Com
8. Well No. 1
9. Pool name or Wildcat Und. Happy Valley Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3342' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Repair P&A Well
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter 0 : 990 Feet From The South Line and 1980 Feet From The East Line Section 29 Township 22S Range 26E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Repair P&A Well <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 8-16-90. RU Schlumberger. RIH to 4318'. Tag cement plug.  
8-17-90. Set wireline bridge plug in the shoe joint at 2465' GL measurement. Set 105' cement plug 2465-2360'. Observed by Johnny Robinson, NMOCD, Artesia, NM.  
8-18-90. Set wireline bridge plug at 1675' w/35' cement plug 1675-1640'.  
Final tag @ 1640'. Witnessed by Mike Stubblefield, NMOCD, Artesia, NM.  
8-24-90. RU Glen's Water Well Service. Bail out drilling mud and 1/2 BO to 1015'.  
SD 35 minutes. FFL 1015'. No fluid entry. Witnessed by Johnny Robinson, NMOCD, Artesia, NM.  
Rig down and revert well to rancher.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 9-6-90  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS

OCT 4 1990

APPROVED BY SUPERVISOR, DISTRICT II TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY: