

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

RECEIVED

1. oil ☒ gas ☐ other ☐

2. NAME OF OPERATOR

TXO Production Corp.

NOV 2-89

3. ADDRESS OF OPERATOR

415 W. Wall, Ste. 900, Midland, TX 79701
O. C. D.
WATKINS, OFFICE

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FSL & 660' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Drilling Operations / TA ☐

5. LEASE
NM-01165

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yates Federal

9. WELL NO.

6

10. FIELD OR WILDCAT NAME

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 18, T-20-S, R-29-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3264.8' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-10-89 Spudded well @ 5:30 p.m. RU & rn 5 jts 13-3/8", 48#, H-40, ST&C csg & cmt w/230 sxs
Cl "C" w/2% CaCl. Circ 10 sxs. PD @ 8:30 p.m., WOC 10.5 hrs.

10-11-89 Drld outshoe & cmt. Made trip for bit & resume drilling.

10-12-89 Drld to 1209' and rn 29 jts 9-5/8", 36#, K-55, ST&C csg & set @ 1209'. Cmt'd w/500 sxs
cmt. PD @ 5:30 a.m., 10/13/89. Circ 100 sxs to pit. WOC.

10-13-89 Resume drilling.

thru
10-15-89

10-16-89 TD 8-3/4" hole and rn 74 jts 7", 20# & 23# csg. Set & cmt @ 3107' w/600 sxs cmt (total).
PD @ 6:00 p.m., 10/16/89. Corc tp sirf/ WPC 11-3/4 hrs. Set slips & CO csg. NUWH & BOP
Stack.

SEE ATTACHMENT FOR CONTINUED REPORTS OF OPERATIONS & TEMPORARY ABANDONMENT

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED M. C. Wesley TITLE Secretary DATE 10/20/89

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED FOR A COPY
Adm

OCT 31 1989

*See Instructions on Reverse Side

CAR 3840