

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO

NM-64594

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cabin Lake 34 Federal

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Cabin Lake

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 34, T21S, R30E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Harvey E. Yates Company

3. ADDRESS OF OPERATOR

P.O. Box 1933, Roswell, N.M. 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State agreement.
See also space 17 below.)
At surface Unit P; 330' FSL & 790' FEL

14. PERMIT NO.

30-015-26631

15. ELEVATIONS (Show whether DF, BY, GR, etc.)

3192.2 GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) csg & cmt jobs

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

2/6/91 TD 17 1/2" hole @ 401'
Ran 9 jts 13 3/8" 54.5# csg; Set @ 401'
Cmtd w/250 sks 12/3 RFC + 500 sks Cl "C" w/2% CaCl
PD @ 11:30 am 2/6/91; Did not circ; Waited 6 hrs
**Ran Temp Survey; TOC @ 140'
Run 1" in hole; Circ 10 sks to pit
WOC 12 hrs; Test csg to 600#/30 min-Held ok

2/12/91 TD 12 1/4" hole @ 3420'
Ran 81 jts 8 5/8" 32# csg; Set @ 3420'
Cmtd w/1600 sks 65/35 "C" poz w/2% CaCl + 200 sks Cl "C" w/2% CaCl
PD @ 8:00 pm 2/12/91; Did not circ; Waited 6 hrs
**Ran Temp Survey; TOC @ 420'
Run 1" in hole; Circ 5 sks to pit
WOC 12 hrs; Test csg to 1200#/30 min-Held ok

**Temperature Surveys will be forwarded ASAP.

18. I hereby certify that the foregoing is true and correct

SIGNED V. Teel V. Teel

TITLE Production Analyst

DATE 2/14/91

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

SSS