

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM01119

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Welch-Yates C Fed.

9. WELL NO.

Riggs #7

10. FIELD AND POOL, OR WILDCAT

Cedar Hills

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 5-T21S-R27E, NMPM

12. COUNTY OR PARISH

EDDY

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Lease Water Disposal

2. NAME OF OPERATOR

Bill Taylor

3. ADDRESS OF OPERATOR

1106 N. Country Club, Carlsbad, NM 88220

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

4122' FNL & 330' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3231' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other) Cementing Surface Casing XX

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- Dec. 16, 1991: Ran 398' of 8 5/8" Surface Casing; cemented with 200 sks. Type II (B) cement through casing, followed by plug; only 10 gallons or so drilling fluid circulated & fell back slowly; (witnessed by NMOCD & BLM personnel). Cement tagged at 140'.
- Dec. 18, 1991: Placed 34 sks Type II (B) through 1" tubing; no circulation to surface (witnessed by BLM personnel). Cement tagged at 80'.
- Dec. 19, 1991: Placed 30 sks Type II (B) through 1" tubing; no circulation to surface (witnessed by onsite BLM personnel). Cement tagged at 40'.
- Dec. 20, 1991: Dumped 2 yards Redi-Mix pea gravel mixture from surface (witnessed by onsite BLM personnel). Cement tagged at 30'.
- Dec. 23, 1991: Dumped 1 1/4 yards Redi-Mix from surface (approved by BLM personnel). Cement came to surface.

18. I hereby certify that the foregoing is true and correct

SIGNED

Bill Taylor

TITLE

Operator

DATE

12/26/91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side