

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

OCT 16 1993

WELL API NO. 30-015-27463
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3070
7. Lease Name or Unit Agreement Name  Wagon Unit
8. Well No. 1
9. Pool name or Wildcat Undesignated Yeso
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4283' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210 (505) 748-1471	4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 32 Township 22S Range 23E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Test well in Yeso openhole below the 9-5/8" casing. <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-7-93. RUPU. NU tubing head and installed BOP. TIH with bit and 2-7/8" tubing to 2870'. Tagged cement plug at 2870'. TOH with 2-7/8" tubing and bit. TIH with bit, scraper and 2-7/8" tubing to 2690'. Circulated casing with 2% KCL water. TOH with 2-7/8" tubing, scraper and bit. Dumped 3100# of frac sand. SD overnight.

10-8-93. TIH with 2-7/8" tubing. Tagged sand. Respot sand from 2870-2800'. Tagged sand at 2800'. TOH with 2-7/8" tubing. TIH with 3 joints 2-7/8" tail pipe, packer and 2-7/8" tubing. Set packer at 2629'. RU swab. Swabbed 5 hours with no shows.

10-9-93. Acidized open hole with 1000 gals 20% NEFE acid. Swabbed well. No shows. Unset packer at 2629'. TOH with 2-7/8" tubing, packer and tail pipe. TIH with 2-7/8" tubing open-ended. Shut down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 10-15-93  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE VALLIAGAS

APPROVED BY SUPERVISOR, DISTRICT I TITLE DATE OCT 22 1993

CONDITIONS OF APPROVAL, IF ANY: