

WELL TEST INTERF F. LON REPORT #:139402		PAGE: 2,
CLIENT : General Atlantic Res. , Inc.		19-FEB-94
REGION :CSD	SEQUENCE OF EVENTS	FIELD:E.AvalonMorrow
DISTRICT:Midland		ZONE :Atoka
BASE :Hobbs N.M.		WELL :BFDU #41
ENGINEER:Mark Luna		LOCATION:S27-20S-28E

DATE	TIME (HR:MIN)	DESCRIPTION	ET (MINS)	BHP (PSIA)	WHP (PSIG)
17-FEB	13:32	Set Packers	-2		
	13:34	Start Flow on 1/8 Choke	0	790	1.5*
	13:39	Good Blow Reading in PSI	5		2.5
	13:49	Strong Blow	15		20.0
	13:58		24		88.0
	13:59	End Flow & Start Shutin	25	773	88.0
	14:03	Gas to Surface	29		
		Rate was 31 MCF on 1/8			
	14:16	End Shutin	42	5142	
	14:17	Started Leak Down Hole	43		
	15:04	Seat Failed	90		
	15:14	Recycled & Set More Weight	100		
		Still no Seat			
	15:15	Pulled Loose	101	5197	