

YATES PETROLEUM CORPORATION
Anemone ANE Federal #2
Section 9-T22S-R24E
Eddy County, New Mexico

DRILL STEM TEST RESULTS

DST #1 7970-8068' (Canyon): TIMES: TO 30"; SI 60"; TO 60"; SI 120"; TO 60"; SI 60".
RECOVERY: 4026' of formation water. SAMPLER: 1.60 cfg, 2200 cc water. PRESSURES:
IHP 3906; IFP 829-1450; ISIP 1921; 2nd FP 1035-1737; 2nd SIP 1901; 3rd FP 1450-1819;
3rd SIP 1860; FHP 3906.

DST #2 8100-8172' (Canyon): TIMES: TO 30"; SI 60"; TO 60"; SI 120"; SI 60"; TO 60".
RECOVERY: 1005' of oil, 232' of rathole mud and 3083' of formation water. SAMPLER:
.65 cfg, 300 cc oil and 2100 cc water. PRESSURES: IHP 4000; IFP 663-982; ISIP
1977; 2nd FP 1098-1664; 2nd SIP 1977; 3rd FP 1664-1920; 3rd SIP 1977; FHP 4000.

DST #3 8168-8230' (Canyon): TIMES: TO 30"; SI 60"; TO 60"; SI 120"; TO 60"; SI 60".
RECOVERY: 613' of rathole mud & 782' of formation water and 3108' of oil. SAMPLER:
1.42 cfg, 1200 oil and 1000 cc water. PRESSURES: IHP 4049; IFP 434-787; ISIP 1942;
2nd FP 746-1364; 2nd SIP 1921; 3rd FP 1346-1614; FHP 4049.

DST #4 8230-8270' (Canyon): TIMES: TO 30"; SI 40"; TO 60"; SI 120"; TO 60".
RECOVERY: 886' of rathole mud & 3436' of formation water. SAMPLER: 2500 cc water.
PRESSURES: IHP 3943; IFP 317-953; ISIP 2005; 2nd FP 1069-1721; 2nd SIP 2005;
3rd FP 1777-2005