				- .			101		
	' UNITED STATES PARTMENT OF THE IJ JREAU OF LAND MANA	NTERIOR 1)וו לסו -DIV Gran	ns. Dist. 2 _{Exp} d Aveau	FORM APPROVED OMB NO. 1004-0135 pres: November 30, 20	00		
SUNDRY I	NOTICES AND REPO	RTS ON WELLS	Artesia	a, NM	88210	677			
Do not use this abandoned wel	s form for proposals to I. Use form 3160-3 (AP	drill or to re-enter D) for such propos	an als.			Illottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						 If Unit or CA/Agreement, Name and/or No. NMNM91035 			
1. Type of Well Gas Well Oth	her	2213	1415767>	Tes y	8. Well Name BONE FI				
2. Name of Operator MARATHON OIL COMPANY	Contact:	(None Specified)	Ą		9. API Well N 30-015-2	No. 18529-00-S1			
3a. Address P O BOX 552 MIDLAND, TX 79702		3b. Phone No. (includ Ph: 915,682.162	ECEIVED			Pool, or Exploratory ER DRAW			
4. Location of Well (ootage, Sec., T.	, R., M., or Survey Description		ARTESI		11. County of	r Parish, and State			
Sec 12 T21S R23E Mer NWS	W 1980FSL 760FWL		مريد م	* . •	EDDY C	OUNTY, NM			
12. CHECK APPF	ROPRIATE BOX(ES) T	O INDICATE NAT	URE OF NO	DTICE, R	EPORT, OR	OTHER DATA			
TYPE OF SUBMISSION			TYPE OF A	ACTION					
□ Notice of Intent	□ Acidize	🗖 Deepen		Produc	tion (Start/Res	ume) 🔲 Water	Shut-Off		
	□ Alter Casing	🗖 Fracture Tr		Reclam			l Integrity		
Subsequent Report	uent Report Casing Repair		□ New Construction □ Recom			-			
Final Abandonment Notice	 Change Plans Convert to Injection 				prarily Abandon Disposal				
13. Describe Proposed or Completed Ope			nated starting (nd approximate duratio	n thereof.		
If the proposal is to deepen directional Attach the Bond under which the woo following completion of the involved testing has been completed. Final At determined that the site is ready for f	ally or recomplete horizontally rk will be performed or provid d operations. If the operation ro bandonment Notices shall be fi	, give subsurface location e the Bond No. on file wi esults in a multiple comp	ns and measure th BLM/BIA. letion or recorr	d and true v Required supletion in a	ertical depths of ibsequent reports new interval, a I	all pertinent markers a s shall be filed within 3 Form 3160-4 shall be fi	ind zones. 0 days iled once		
Work to install gas assisted pl pump, POOH w/tbg & RIH w/r PU. 7/18/01 - MIRU PU, ND & 8040' & POH LD tbg, bit & DC tubing. Installed hanger and I bottom of tubing @ 8012'. Tu	mills & bailer to 7950'. P wellhead & NU BOPs. P Cs. RU gas lift mandrel & landed in wellhead. ND I	OOH w/tbg & LD mil OOH w/killstring & F CT unit. RIH w/ma 30Ps, NU wellhead	ls & bailer. RH w/bit & D ndrel, seatir & RD PU. (RIH w/kill Cs. RIH	string. ND BC w/tbg to hard CT string b: Irel @ 8009 T	OPs, NU wellhead tag @ 7942', drill anded to 2-7/8", J- septing ripple @ &	& RD out to 55 004'		
14. I hereby certify that the foregoing is	s true and correct. Electronic Submission	#7268 vorified by the		formation					
					•				
	For MARAT	HON OIL COMPANY, processing by linda a	sent to the C skwig on 09/	24/2001 (0	1LA0897SE)				
	For MARAT Committed to AFMSS for	HON OIL COMPANY, processing by linda a Title	sent to the C skwig on 09/	24/2001 (0	1LA0897SE)				
Name (Printed/Typed) (None Sp	For MARAT Committed to AFMSS for	processing by linda a Title	skwig on 09/	24/2001 (0	1LA0897SE)				
	For MARAT Committed to AFMSS for p pecified)	processing by finda a Title	skwig on 09/ 09/24/200	1					
Name (Printed/Typed) (None Sp	For MARAT Committed to AFMSS for p pecified)	processing by linda a Title	skwig on 09/ 09/24/200	1					
Name (Printed/Typed) (None Sp	For MARAT Committed to AFMSS for p pecified)	OR FEDERAL OF	skwig on 09/ 09/24/200	1		Date			

** REVISED **

		Spud: 06/21/95 G.L. Elev.: 3741' K.B.: 3757' 13 5/8" Conductor Casing Set at 16', Cement to Surface W readi-mix. Intermediate Casing 9 5/8" 36#, J-55 Csg. Set at 1200', Cmt. W/820 sks.			Bone Flats #3 Surface Location: U.L. "L", 1980' FSL, 760' FWL BHL - Lateral #1: 1684' FSL & 1925' FWL BHL – Lateral #2: 2362' FSL & 1785' FWL Sec. 12, T-21-S, R-23-E Eddy Co., N.M. Lease No.: NM-81677 API No.: 30-015-28529					
		Well Name:	Bone Flats 12 # 3			_		Date Job:	7/30/2001	
		Co. Man:	Tim Winters				·	KB:	15	
		# Joints	Size	Weight	Grade	Cplg	Length	Тор	Bottom	
							K.B.C.	0.00	15.00	
		256	2 7/8"	6.5#	J-55	8rd	7984.96	15.00	7999.96	
			Gas lift mandrel				3.00	7999.96	8002.96	
			Seating nipple				0.66	8002.96	8003.62	
			3 1/2"	sub w/ XO			8.55	8003.62	8012.17	
		249	Total # Joints			1	1			
		Size: Comments:	Pump Report 2 8003' averted to gas assist plunger lift.							
		No. of Jts & Rods Returned : Returned 249 jts of J-55 tbg Ran 256 jts of J-55 C2 tbg. Perfs: 7778'-7868' w/4spf; Squeezed 8/98								
			, o , o o o m	opi, oquee	200 0/ 20					
		Plunger a	ssembly		SE Lateral #1 – Drilled & Completed 12/8/97					
	←	Gas Lift	Open Hole 7777'-8984' MD 7774'-7790' TVD; KOP 7720'							
	Standing Valve @ 8003'					NE Lateral #2 – Drilled & Completed 12/8/98 Open Hole 8137'-9055' MD 7842'-7789' TVD; KOP – 7777'				
			n Casing 6#, K-55 Csg. 0', Cmt. W/112	25 sks., Circ	. 75 sks.					
	\leq	PBTD: 804 . TD: 8050'	10'							

~

WELL HISTORY Bone Flats #3

8/3/95 Initial Completion in the South Dagger Draw Pool. Perforated from 7778'-7868' using HEG's gun loaded with 23 GM tungsten charges. Spotted 15% NEFE HCL acid and treated in 2' increments using PPI tool with 125 gallons per increment.

8/8/95 RU Arc Pressure and ran gradient survey BHP - 1765 psi.

8/9/95 RIH w/ Submersible pump (Size ?).

11/2/95 Pulled Sub pump. Found Burned Motor.

11/29/95 Pulled Sub pump. Found burned motor.

1/25/96 Pulled Sub pump. Found burned motor. Replaced w/ 2- TD-750 pumps.

2/24/96 Rod up.

10/14/96 Fish parted rods. Found large amounts of paraffin on rods.

12/13/96 Pull to check for paraffin. Found large amounts of soft paraffin on rods.

2/20/97 Fish parted rods.

6/7/97 Fish parted rods.

6/17/97 Repair pump, and pull tubing to repair tubing leak.

10/5/97 Fish parted rods.

11/4/97 Prep for lateral. KOP 7720'

12/2/97 RU B.J. Coiltech Vortex tool on 1.75" coil. Acidize lateral w/ 425 bbls of 15% HCL.

12/8/97 RIH w/ sub pump.

3/17/98 Pull Bad sub pump

3/26/98 Fish Sub pump.

4/8/98 Pushed Junk to 7930'

4/9/98 RIH w/ 2 R9 submersible pumps.

5/25/98 Pulled bad sub pump.

7/6/98 Sub pump grounded down hole.

7/26/98 Acidize & clean lateral.

Well History (continued)

8/18/98 Squzd perfs from 7778-7868' using 75 sks. of THIX tailed w/ 300 sacks of "H" neat. Drilled out Cement and tagged PDTD @ 7950'.

9/27/98 RIH w/ gauge ring and junk basket. Tagged junk @ 7805'. RIH and set CIBP @ 7798. Drill second lateral.

10/24/98 RIH w/ 2 R9 submersible pumps.

10/31/98 Acidize lateral

11/7/98 Swab and downsize sub pump.

11/21/98 Acidize lateral

12/3/98 RIH w/ FC-450 submersible pump.

1/29/99 Twisted shaft. PBTD 7950'

2/25/99 Rod up. (rotoflex)

7/31/01 Install Gas Assisted Plunger Lift system.