Do not use this form f	UNITED DEPARTMENT O BUREAU OF LAN NORY NOTICES AND R OF PROPOSALS TO drill OF TO CAPPLICATION FOR PER SUBMIT IN	F THE INTERI D MANAGEMI REPORTS ON N deepen or ree	ENT U////// WELLS Intry to a diffe rent rese	Drawer ArteBi 5. NM- 6. rvoir.	CONS COMMISSION DD FORM APPROVED Expires: March 31, 1993 Lease Designation and Serial No. 07260 If Indian, Allottee or Tribe Name If Unit or CA, Agreement Designation Idian Hills Unit
1. Type of Well Oil Well Gas Well			May Maria		Well Name and No.
2. Name of Operator Indi					ian Hills Unit 44488
					API Well No. 509
					Field and Pool, or exploratory Area ian Basin (U. Penn-Assoc.)
					County or Parish, State
	N-24-L				Eddy Co. N.M.
12. CHECK APP	ROPRIATE BOX(s) TO	NDICATE N	ATURE OF NOTICE, F	REPORT, (OR OTHER DATA
	TYPE OF SUBMISSION TYPE OF AC				
Notice of Inte		F	Abandonment Recompletion		Change of Plans New Construction
X Subsequent R	eport	<u> </u>	Plugging Back Casing Repair		Non-Routine Fracturing
Final Abando	nment Notice	<u> </u>	Altering Casing		Water Shut-Off Conversion to Injection
9/4/95: MIRU Comp 6275'-6360 9/5/95: RIH and t 9/6/95: RU wireli gram tungs 9/7/95: RIH with Pinpoint I Set packer 9/8/95-9/9/95: Sw 9/10/95: POOH wit Charges. 9/11/95: Using PF Swabbing. 9/12/95-9/13/95: 9/14/95: POOH wit 9/15/95: Installe completic 9/16/95: Tied in 9/17/95: Kicked w 9/21/95: MIRU PU	pletion Unit. NU b). Fell out of c agged PBTD @ 8269 ne Co. Ran GR/CC ten carbide charg PPI tool to 8249 njection Packer a @ 7926 after tre abbed back for tw h PPI tool. Perf RIH and set RBP I tool acidized 7 SDFN Swabbed well. h treatment strin d ESP on 2 7/8" L m Unit. wellhead. Power ell off to test @ NU BOP POOH W/	and test B(ement. Test . Displac L. Perfora es.(2JSPF). . Pickelec cidized 804 atment. St o days. ed 7976-802 from wirel 976-8022 wi g an RBP. -80 tubing. outage. SDF 11:00 AM. pump and Th	DP. C/O string. Sted casing to 15 ced holed with 2% ated 8128-8044 wi RD wireline Co. 2 7/8" tubing w 4-8128 with a to carted swabbing. 2 with 2 JSPF us ine @ 8040'. RIH th a total of 62 SDFN. Pump intake @ N Test all water	Drilled 00 PSI. KCL. P(th 3 1/8 RIH w ith 500 tal of SDFN ing 23 (with PI 50 gall(3 EC 7963 7963	NE BOP 'U tree. RDMO
14. I hereby certify that the fore	joing is true and correct				
(This space for Federal or Sta		Title AUVd	nced Engineering		Date <u>9/29/95</u>
Approved by Title					Date
Conditions of approval, if an Title 18 U.S.C. Section 1001 m		ingly and will 1			0 1 1 1995
of representations as to any matter	within its jurisdiction.	mgry and wnifully to	make to any department of agency	y of the United	States any false, fictitious or fraudulent statements

INDIAN HILLS UNIT # 8 COMPLETION

.

9/23/95: Set 2 7/8' Straddle Liner 8031-7932 isolating perfs 7976-8022'. 9/24/95: RIH with submersible pump on 2 7/8": tubing.. Pump intake @ 7852'. 9/25-9/26: Pulled and reran due to bad cable splice. Pump intake set @ 7852'. NDS BOP. NU wellhead. Turned well into test tanks.