

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

OXY USA Inc.

16696

3. Address and Telephone No.

P.O. Box 50250 Midland, TX 79710 915-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2085 FSL 2085 FEL NWSE(1) Sec 15 T20S R28E

5. Lease Designation and Serial No.

NM0554216

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Government AC #3

9. API Well No.

30-015-28627

10. Field and Pool, or Exploratory Area

Old Mt. Herman Ranch

Blue Springs Pool

11. County or Parish, State

Edley NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Spud, Set Casing & Cement
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See other side

RECEIVED

OIL & GAS DIV.

SEP 2 8

14. I hereby certify that the foregoing is true and correct

Signed

David Stewart

David Stewart

Title

Regulatory Analyst

Date

2/6/96

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

ATTACHMENT 3160-5
OXY USA INC.
GOVERNMENT AC #3
SEC 15 T20S R28E
EDDY COUNTY, NM

NOTIFIED BLM @ 1500hrs MST 1/22/96 OF SPUD DATE & TIME. MIRU EXETER #67, SPUD WELL @ 2030hrs MST 1/23/96. DRILL 17-1/2" HOLE TO TD @ 405' , 0330hrs MST 1/24/96, CHC. RIH W/ 13-3/8" 48# CSG & SET @ 405'. M&P 220sx CL C CMT FOLLOWED BY 200sx CL C CMT W/ 2% CACL2, PLUG DOWN @ 0900hrs MST 1/24/96, CMT DID NOT CIRCULATED, WOC-8hrs. BLM NOTIFIED, DON EARLY WITNESSED FIRST PLUG. RIH W/ 1" TBG & TAG @ 97', M&P 150sx CL C CMT W/ 2% CaCl2, POOH, WOC. RIH W/ 1" & TAG @ 25', M&P 50sx CL C CMT W/ 5% CACL2, CIRC CMT TO PIT, WOC 3hrs. CUT OFF CSG & WELD ON STARTING HEAD, NU BOP & TEST TO 1000#, HELD OK. RIH, TAG CMT @ 305' & DRILL AHEAD.

DRILL 11" HOLE TO TD @ 3000', 0730hrs MST 1/30/96, CHC. RIH W/ 8-5/8" 24-32# CSG, WASH DOWN FRO 2348' TO 2864'. CSG STUCK 136' FROM BOTTOM. TRY TO WORK CSG UP & DOWN W/O SUCCESS, TRY TO CIRC CSG W/O SUCCESS. RUWL, RIH W/ FREEPOINT, PIPE 100% FREE @ 1550' & 100% STUCK @ 1575', POOH. ND BOP, SET SLIPS & CUT CSG, WELD ON SLIP COLLAR FOR HEAD, NU BOP. RIH W/ 7-7/8" BIT & DRILL OUT FLOAT COLLAR & SHOE TO TD @ 3000', POOH. RIH W/ 8-5/8" RTTS PKR & SET @ 2797'. PRESS 8-5/8" X 4-1/2" ANNULUS TO 2200#, ATTEMPT TO EIR DOWN DP, PRESS TO 3700#, REL PKR, POOH. PERF 4 SQUEEZE HOLES @ 1500', EIR OF 4BPM @ 1000#, M&P 400sx CL C CMT 65:35 POZ FOLLOWED BY 200sx CL C CMT W/ 2% CACL2, WOC 4hrs. RIH W/ TEMP SVY, TAG @ 1512', NO CMT BEHIND PIPE. RIH W/ 2nd SVY, SAME RESULTS. RIH W/ CMR RET & SET @ 1403', EIR OF 2.5BPM @ 1500#, M&P 100SX CL H W/ 10#/sx GYP, DISP TO CR, STING OUT OF CR & DUMP 1sx CMT ON CR, ND BOP, NDWH, PULL 8-5/8" SLIPS. PER BLM, SHANNON SHAW'S APPROVAL, RIH W/ 1" TBG & TAG @ 600', COULDN'T GET DEEPER, CMT W/ 50sx CL H CMT W/ 10# GYP, POOH, WOC 1.5hrs. RIH W/ 1" & TAG @ 505', CMT W/ 50sx CL H CMT W/ 10# GYP, POOH, WOC 1.5hrs. RIH W/ 1" & TAG @ 503', CMT W/ 200sx CL C CMT 65:35 POZ, POOH, WOC 2hrs. RIH W/ 1" & TAG @ 455', CMT W/ 125sx CL C CMT W/ 3% CACL2, POOH, WOC 2hrs. RIH W/ 1" & TAG @ 68', CMT W/ 45sx CL C CMT W/ 3% CACL2, CMT CIRCULATED, POOH, WOC 4hrs. NU WH & BOP & TEST TO 2000#, HELD OK, RIH & TAG @ 1390'. DO CR & 180' CMT, TIH TO 2848' & WASH DOWN TO 3000', CHC. RIH W/ BHA, ATTEMPT TO RESUME DRLG & LOST ALL RETURNS. RIH W/ RTTS & SET @ 1625', TEST SQZ HOLES @ 1500' TO 800#, EIR DOWN DP OF 5.5BPM @ 800#. RIH & SET CMT RET @ 2743', PRESS CSG TO 500# HELD OK. EIR OF 4BPM @ 200#, M&P 275SX CL C 65:35 POZ W/ 6% GEL + 5#/sx SALT + .25# CELLOPHANE + 10# GILSONITE, FOLLOWED BY 200sx THIXOTROPIC CMT, POOH, WOC-8hrs. RIH & TAG @ 2733', CR & CMT TO 2850', FELL FREE, CHC, POOH. CHANGE BHA & BIT, RIH & DRILL AHEAD W/ FULL CIRCULATION, 2/5/96.