

YATES PETROLEUM CORPORATION
Spring ART Federal #1
Section 23-T20S-R26E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7624-7654': TIMES: TO 20"; SI 60"; TO 90"; SI 180"; TO 90". RECOVERY: 15.7 bbls oil and 11.2 bbls water. SAMPLER: 5.32 cfg, 700 cc oil and 900 cc water. PRESSURES: IHP 4188; IFP 2313-2369; ISIP 2564; 2nd FP 2397-2229; FSIP 2509; FFP 2229-2257; FHP 4188

DST #2 8194-8240': TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY: 4557' of formation water. SAMPLER: .83 cfg and 2400 cc water. PRESSURES: IHP 4406; IFP 601-985; ISIP 2963; FFP 1072-2209; FSIP 2965; FHP 4365

DST #3 8238-8290': TIMES: TO 20"; SI 60"; TO 90"; SI 180". RECOVERY: 5637' of formation water. SAMPLER: Trace of gas and 2600 cc water. PRESSURES: IHP 4373; IFP 406-932; ISIP 2983; FFP 932-2470; FSIP 2984; FHP 4375

DST #4 8363-8425': TIMES: TO 20"; SI 60"; TO 887"; SI 35". RECOVERY: 6385' of water. SAMPLER: 2600 cc water. PRESSURES: IHP 4282; IFP 2285-2668; ISIP 3038; FFP 3024-3038; FSIP 3039; FHP 4279