

CONOCO STATE #302/12/98

TMD: 6590 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 06:30 02A A DRILLING 6262-6292 (30') SURVEY 2.75 DEG-
 6245
 06:30 07:15 06A A TRIPPING FOR BIT
 07:15 09:45 08B A RIG REPAIR / CAT HEAD CHAIN
 09:45 12:00 06A A TRIPPING FOR BIT /LD TRI DRILL COLLAR
 12:00 14:00 06A A TRIPPING IN HOLE /PICK UP 1 DC+REAMING IBS
 14:00 14:30 06A A TRIPPING WASH 30' TO BOTTOM
 14:30 19:45 02A A DRILLING 6292-6390 (98')
 19:45 20:15 10A SURVEYS 3.0 DEG-6350
 20:15 00:15 02A A DRILLING 6390-6486 (96')
 00:15 00:45 10A SURVEYS 2.75 DEG-6446
 00:45 04:15 02A A DRILLING 6486-6583 (97')
 04:15 04:45 10A SURVEYS 3.0 DEG-6543
 04:45 05:00 02A A DRILLING 6583-6590 (7')

02/13/98

TMD: 6965 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 08:00 02A A DRILLING 6590-6679 (89')
 08:00 08:30 10A SURVEYS 3.0 DEG-6639
 08:30 12:00 02A A DRILLING 6679-6775 (96')
 12:00 12:45 10A SURVEYS 3.75 DEG-6735
 12:45 17:30 02A A DRILLING 6775-6869 (94')
 17:30 18:00 10A SURVEYS 4.25 DEG-6829
 18:00 23:45 02A A DRILLING 6869-6901 (68')
 23:45 00:15 10A SURVEYS 4.25 DEG-6861
 00:15 04:30 02A A DRILLING 6901-6965 (64')
 04:30 05:00 10A SURVEYS 4.50 DEG-6925

02/14/98

TMD: 7296 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 10:45 02A A DRILLING 6965-7058 (93')
 10:45 11:15 10A SURVEYS 3.75 DEG-7018
 11:15 16:45 02A A DRILLING 7058-7123 (65')
 16:45 17:15 10A SURVEYS 3.0 DEG- 7083
 17:15 00:15 02A A DRILLING 7123-7217 (94')
 00:15 00:45 10A SURVEYS 1.50 DEG- 7217
 00:45 05:00 02A A DRILLING 7217-7296 (79')

02/15/98

TMD: 7715 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 05:00 02A A DRILLING 7296-7715 (419') W/ FULL RETURNS

02/16/98

TMD: 8015 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 08:00 02A A DRILLING 7715-7758 (43)
 08:00 08:30 10A SURVEYS 2.75 DEG-7716
 08:30 20:00 02A A DRILLING 7758-7916 (158')
 20:00 20:30 10A SURVEYS 2.50 DEG- 7876
 20:30 05:00 02A A DRILLING 7916-8015 (99)