YATES PETROLEUM CORPORATION Jacque AQJ State #1 Section 34-T21S-R31E Eddy County, New Mexico

## SUNDRY NOTICE CONTINUED:

Could not move pipe. Pipe stuck by sand. Attempted to circulate down casing. Plugged. Attempted to circulate down tubing - plugged. 5-23-98 - Tubing stuck at 7830'. Rigged up Halliburton Coiled Tubing Unit. TIH with coiled tubing. Tagged sand at 7600'. Circulated down to 7900'. Pulled coiled tubing back inside tubing to 7100'. Rigged up pump truck on casing. Tried to pump tubing free. Casing pressure would leak off but would not free up. Started back down with coiled tubing. Circulated sand down to PBTD of 8076'. Pulled back up inside tubing. Pumped on casing. Tubing came free. Circulated well clean. TOOH with coiled tubing. Rigged down coiled tubing. TOOH with tubing. Turned well over to production to run pump and rods.

Rusty Klein

Operations Technician May 28, 1998