Well Name and Number: Moo Cow State #1

Location: Sec. 5, T21S, R27E, Eddy County, New Mexico

Operator: Oxy USA, Inc.

Drilling Contractor: McVay Drilling Company

The undersigned certifies that he is an authorized representative of the drilling contractor who drilled the above described well and that he has conducted deviation tests and obtained the following results:

Degrees @ Depth		Degrees @ Depth		Degrees @ Depth		
1/4	222	1	5065	1 3/4	9790	
1/2	425	1 1/4	5558	1 3/4	10257	
1	604	1 3/4	6054	1 1/4	10559	
1 ½	1097	2	6301	1 ½	10989	
1 1/2	1258	1 3/4	6457	1 1/2	11531	
3/4	1481	1 ½	6581			
1	1971	1 ½	6908			
3/4	2218	1 1/4	7207			
3/4	2464	1	7676			
1/2	2607	1	8188			
1/2	3090	1 3/4	8477			
3/4	3583	2	8800			
3/4	4080	1 ½	9119			
3/4	4571	1	9409			

Drilling	By:
Subscribed and sworn to before me this 274	t day of may, 1998.
	Notary Public
My Commission Expires: $6-16-21$	Lea County, New Mexico