Well Name and Number: Moo Cow State #1

Location: Sec. 5, T21S, R27E, Eddy County, New Mexico

Operator: Oxy USA, Inc.

Drilling Contractor: McVay Drilling Company

The undersigned certifies that he is an authorized representative of the drilling contractor who drilled the above described well and that he has conducted deviation tests and obtained the following results:

Degrees @ Depth		Degrees @ Depth		Degrees @ Depth		
			500 <i>1</i>	1 %	9790	
1/4	222	1	5065			
1/2	425	1 %	5 <b>55</b> 8	1 1⁄4	10257	
1	604	1 3/4	6054	1 1/4	10559	
1 1/2	1097	2	6301	1 1/2	10989	
1 1/2	1258	1 1/4	6457	1 1/2	11531	
3/4	1481	1 ½	6581			
1	1971	1 ½	6908			
3/4	2218	1 1⁄4	7207			
3/4	2464	1	7675			
1/2	2607	1	8188			
1/2	3090	1 3/4	8477			
3/4	3583	2	8800			
%	4080	1 1/2	9119			
3/4	4571	1	9409			

Drilling Contractor: MeVay Drilling Company By:	
Subscribed and sworn to before me this 74 day of maly , 1998.	•
Notary Public	

My Commission Expires: 6-11-01

Lea County, New Mexico