

WELL TEST INTERPRETATION REPORT #:1187971		PAGE: 12.
CLIENT : DEVON ENERGY CORPORATION		31-AUG-98
REGION :CSD	DISTRIBUTION OF REPORTS	FIELD:CATCLAW DRAW
DISTRICT:HOBBS		ZONE :DELAWARE
BASE :MIDLAND		WELL :PURE FED. #3
ENGINEER:KIRK BEASLEY		LOCATION:11-21S-25E

SCHLUMBERGER has sent copies of this report to the following:

=====

DEVON ENERGY CORPORATION  
 20 N. BROADWAY  
 SUITE 1500  
 OKLAHOMA CITY, OK 73102  
 Attn: GEORGE DAVIS  
 ( 2 copies)

MATADOR PETROLEUM  
 405 W. WALL STREET  
 MIDLAND, TX 79701  
 Attn: MIKE MILLER  
 ( 2 copies)

Any interpretations or recommendations are opinions and necessarily based on inferences and empirical factors and assumptions, which are not infallible. Accordingly, Schlumberger (Flopetrol Johnston) cannot and does not warrant the accuracy of correctness of any interpretation or measurement. Under no circumstances should any interpretation or measurement be relied upon as the sole basis for any drilling, completion, well treatment or production decision or any procedure involving risk to the safety of any drilling venture, drilling rig or its crew or any other individual. The Customer has full responsibility for all drilling, completion, well treatment, and production procedure, and all other activities relating to the drilling or production operation.