Submit 3 Copies to Appropriate District Office

(This space for State Use)

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY-

State of New Mexico rgy, Minerals and Natural Resources Departr.

CIST	
------	--

m C-103

P.O. Box 1980, Hobbs, NM 88240

DISTRICTII P.O. Drawer DD, Artesia, NM 88210 OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

Revised 1-1-89		
WELL API NO.		
30-015-30444 5. Indicate Type of Lease STATE X FEE		
STATE X FEE		
VA-636		
7. Lease Name or Unit Agreement Name		
Archimedes ARE State Com 8. Well No.		
9. Pool name or Wildcat		
Cemetary Morrow		
Feet From The West Line		
NMPM Eddy County		
Report, or Other Data SSEQUENT REPORT OF:		
ALTERING CASING		
G OPNS. PLUG AND ABANDONMENT		
EMENT JOB		
ion casing & cement X		
ding estimated date of starting any proposed		
of 5-1/2" 17# & 15.5# casing 50'); 16 joints of 5-1/2" 17# andblasted (598.49'); 25 joints 5-1/2" 15.5# J-55 varnished .78') (Total 9846.69') of ar set at 9798'. Bottom marker 0 sacks Super Modified C, .5% (yield 1.60, weight 13.1). e, OK. WOC. Released rig water. Notified OCD-Artesia		

10-28-99

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS OF WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT LIVED (FORM C-101) FOR SUCH PROPOSAL (\$2) 1. Type of Well: WELL X WELL OTHER 2. Name of Operator i/ YATES PETROLEUM CORPORATION 3. Address of Operator 105 South 4th St., Artesia, NM 88210 4. Well Location E : 1980 Feet From The North Line and hip 21S Range 24E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Township 3818' GR Check Appropriate Box to Indicate Nature of Notice, R 11. NOTICE OF INTENTION TO: SUE PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING **PULL OR ALTER CASING** CASING TEST AND C OTHER: Product OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1103. TD 9840'. Reached TD at 10:50 PM 10-9-99. Ran 233 joints as follows: 30 joints of 5-1/2" 17# N-80 varnished (1242. N-80 sandblasted (662.80'); 15 joints of 5-1/2" 17# J-55 s. of 5-1/2" 17# J-55 varnished (1038.48') and 132 joints of (5652.64') and 15 joints of 5-1/2" 17# J-55 varnished (651)casing set at 9840'. Float shoe set at 9840'. Float coll set at 7336'. Pumped 500 gallons of mud flush ahead of 820 FL52, .5% FL25, 1/4#/sack celloflake and 5#/sack gilsonite PD 10:48 AM 10-13-99. Bumped plug to 1700 psi for 1 minut at 3:00 PM 10-13-99. NOTE: Displaced casing with 2% KCL v of casing and cement - no witness. Waiting on completion unit. frue and complete to the best of my knowledge and belief. Operations Technician Oct. 22, 1999 SIGNATURE -Rusty Klein TELEPHONE NO. 505/748-147] TYPE OR PRINT NAME Sim W. Sung

Ristrict Supervisor