(August 1999) DEPARTMEN	ED STATES I OF THE INTERIOR AND MANAGEMENT	311 S. 1st	Cons. Div	FORM APPR SON OMB NO. 100 Expires: November 5. Lease Serial No.	OVED 4-0135 r 30, 2000	
SUNDRY NOTICES	AND REPORTS OF	B11 S. ISI N WELLS Penter an Artesia, N	M 88210-2	<b>3.</b> Lease Serial No.		
	or proposals to drill or to re- form 3160-3 (APD) for such			6. If Indian, Allottee or T	ribe Name	
SUBMIT IN TRIPLICATE	- Other instructions on	reverse side		7. If Unit or CA/Agreemen	nt, Name and/or No.	
Oil Well X Gas Well Other		61 1		8. Well Name and No. Jones Canyon "4"	Fed #5	
2. Name of Operator Santa Fe Snyder Corporation		14 12	3	9. API Well No.		
3a. Address 550 W. Texas, Suite 1330, Midland,	<u>1X /9/01 (</u>	915)686-6612	ea code)	30-015-30568	0933	
4. Location of Well (Footage, Sec., T., R., M., or Surv. Lot 3, 1374 FNL & 2535' FWL, Sec. 1699' 2576 FEL		R 24E		Indian Basin (Upper Penn) Assoc. 11. County or Parish, State		
				Eddy	<u>NM</u>	
12. CHECK APPROPR	ATE BOX(ES) TO IND	ICATE NATURE OF NO	TICE, REPORT,	OR OTHER DATA		
TYPE OF SUBMISSION		TYPE OF ACTION				
Notice of Intent           X         Subsequent Report	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamation	n Well	or Shut-Off Integrity	
Final Abandonment Notice	Casing Repair Change Plans Convert to Injection	New Construction     Plug and Abandon     Plug Back	Recomplete Temporarily Water Disp	y Abandon <u>Surfac</u>	r <u>Spud &amp; set</u> e Csg.	
<ol> <li>Describe Proposed or Coommpleted Operation (clear If the proposal is to deepen directionally or recomm Attach the Bond under which the work will be per following completion of the involved operations. If testing has been completed. Final Abandonment N determined that the final site is ready for final inspection 2/04/00 Spud 17 1/2" hole @ 2 pr 2/11/00 GIH W/ 36 jts 13 3/8" 54 Class 'C' WOC. Run temp svy, top between plugs. 2/12/00 Pump (3) 100 sack plugs TOC @ 100'. Pump 100 sx plug dow surface. Release United Drilling</li> </ol>	down 1" @ 75' W/ 3%	write locations and measur ad No. on file with BLM/E multiple completion or reco after all requirements, inch oth of 1600'. Cmt W/ D'. GIH W/ 1" to 3% CC waiting 1 H CC WOC. Pump 90	ed and true vertic IA. Required sub mpletion in a new ding reclamation, 75° pump(5) ar between p sx W/ 3% CC	al depths of all pertinent n psequent reports shall be fil interval, a Form 3160-4 have been completed, and 4 + 435 sx Lite + 100 sx plugs w/ plugs. WOC. Run t down 1" @ 75' c	narkers and zones. ed within 30 days shall be filed once the operator has 2500 sx 1 hr	
	*Band kranter					
		L		acs.		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		Title				
Bill Keathly		Regulat Dato 2/16/00	ory_Special	ist		
- Year Arackly This		RAL OR STATE OFF				
Approved by		Title		Date		
Conditions of approval, if any, are attached. Approval o certify that the applicant holds legal or equitable title to	those rights in the subject	ant of office	· <u>,.</u>			
which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section States any false, fictitious or fraudulent statements or represent	1212 makes it a crime f	or any person knowingly of	d willfully to mak	te to any department or age	ency of the United	

// \

CEARDE

S000 EE0 18 ∀ 4:35

Beilden TTEmens Treut Good Anter 198