

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division APPROVED
811 S. 1st Street Budget Bureau No. 1004-0135
Artesia, NM 88210-2834 Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Gas
☒ Well ☐ Well ☐ Other

2. Name of Operator

STRATA PRODUCTION COMPANY

3. Address and Telephone No.

P. O. Box 1030

Roswell, New Mexico 88202-1030 505-622-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL & 330' FWL

Section 25-20S-28E

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Lee Federal #9

9. API Well No.

30-015-31451

10. Field and Pool, or Exploratory Area

Scanlon Delaware

11. County or Parish, State

Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> OTHER <u>Completion Operations</u>	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

03/13/2001: MIRU. NU BOP.

03/14/2001: Perforate 11 .42 holes at 5439'-5447'. Acidize with 1000 gallons 7 1/2% acid. Swab test and evaluate.

03/16/2001: Frac with 45 tons CO2, 19,977# 20/40 sand and 119 bbls gel. RU wellhead. Flowing.

03/19/2001: Set and connect flowline to battery. Flowing. Flow test and evaluate.

RECEIVED
(ORIG. SGD.) DAVID R. GLASS
APR 18 2001
BLM

14. I hereby certify that the foregoing is true and correct

Signed Carol J. Garcia Title Production Records Manager Date 04/06/2001

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____

Conditions of approval, if any:

RECEIVED
APR 09 2004
BLM
SOUTHERN REGION