

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office				
Lease No.	L.C.	9 3305		
Unit				

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	- 	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		
	1	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

				, 19.
Well No. is locate	ed ft	. from $\begin{bmatrix} N \end{bmatrix}$ line an	d $\underbrace{ft.}_{from} ft.$ line of se	с. 17
(½ Sec. and Sec. No.)	7-41-4	2-22-2	3.4.7.W.	
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
VI.1daut				
(Field)	((County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is ______ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well plugged and absorbaned on James 7 19, 1956.

Spotted 30 ms. commet plage at the following intervals: 6150-6260'; 1450-1560'; 850-950'.

Toy of well capped with a steel plate.

to the so casing recovered from well as it is well by Dr. C. L. Vennet, Carlabed, Nov M

i understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.		
Company .	CHIEF OIL COMPANY OF CALLFORNIA	
Address	519 West Tenns Avenue	
	Michael, Penns	By Rue Gallion J.
***************************************		Title Detli (ag 1844.