

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

LAND OFFICE _____

LEASE NO. LC-066046-CUNIT F

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	X
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

HUAPACHE OIL UNIT NO. 1December 8, 1958WELL NO. 3 IS LOCATED 2040 FT. FROM {N} LINE AND 1980 FT. FROM {W} LINE OF SEC. 22SE/4 of NW/4

(1/4 SEC. AND SEC. NO.)

24-S

(TWP.)

24-E

(RANGE)

-

(MERIDIAN)

W/C

(FIELD)

Eddy

(COUNTY OR SUBDIVISION)

New Mexico

(STATE OR TERRITORY)

THE ELEVATION OF THE DERRICK FLOOR ABOVE SEA LEVEL IS later FT.

DETAILS OF WORK

(STATE NAMES OF AND EXPECTED DEPTHS TO OBJECTIVE SANDS; SHOW SIZES, WEIGHTS, AND LENGTHS OF PROPOSED CASINGS; INDICATE MUDDING JOBS, CEMENTING POINTS, AND ALL OTHER IMPORTANT PROPOSED WORK.)

Ran 1779' of 9-5/8" casing (44 jts.) set at 1798'. Cemented with 200 sacks 8% gel cmt. and 150 sacks neat cmt. POB at 8:47 AM 12-5-58. Tested 9-5/8" csg. w/ 1000# for 45 minutes. Test Satisfactory. Drilled plug at 1:00 PM 12-6-58. Drilling.

I UNDERSTAND THAT THIS PLAN OF WORK MUST RECEIVE APPROVAL IN WRITING BY THE GEOLOGICAL SURVEY BEFORE OPERATIONS MAY BE COMMENCED.

COMPANY Humble Oil & Refining CompanyADDRESS Box 2347 - Hobbs, New MexicoORIGINAL
By SIGNED:R. R. ALWORTHTITLE Agent