

-2 31 / N 1650 / N -

NUMBER OF COPIES RECEIVED		5
DISTRIBUTION		
SANTA FE	FILE	1
U.S.G.S.	LAND OFFICE	
TRANSPORTER	OIL GAS	
PRODUCTION OFFICE	OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Martin Yates, III				Address 323 Carper Building; Artesia, N.M.			
Lease Belle Mc Cord		Well No. 2	Unit Letter F	Section 22	Township 23 S	Range 26E	
Date Work Performed 1-7-62		Pool Dark Canyon--Undesignated				County Edgy	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Spotted 25 sacks of cement plug in bottom of hole at 340 feet.
Filled with heavy mud and put five sacks of cement plug at surface.
Filled pits and cleaned location.

RECEIVED

FEB 26 1962

O. C. C.
ARTESIA, OFFICE

Witnessed by Nola Carder	Position Bookkeeper	Company Martin Yates, III
------------------------------------	-------------------------------	-------------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>Howard C. Labley</i>		Name <i>Nola Carder</i>	
Title DISTRICT INSPECTOR		Position Bookkeeper	
Date FEB 26 1962		Company Martin Yates, III	