		/	·	23	C4	/N	r	16	jh:	VV		· · · · · · · · · · · · · · · · · · ·	
U.S.G.S.								IL CONSERVATION COMMISSION FORM C-103 (Rev 3-55) EOUS REPORTS ON WELLS					
SPERATOR	2			(Submit	to appropr	iate D	istric	t Office	as per Com	mission Rule	1106)]	
Name of Com	pany			·		1	Addres	s		<i>"</i>			
Lease Mai	rin Yale	<u>s, I</u>	IV	W	ell No.	32 Unit L	<u>3</u> C.	Section	Township	ng Artes	lia. Range	New Mexico	
	McCord,	<u> </u>		<u> </u>	2	F		22	235		26		
Date Work Pe 1-13-62			Pool Darw	്രവാം	nUnd	ooia			County) 7			
	THIS IS A REPORT OF: (Check appropriate block)												
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):													
Plugging Remedial Work													
Detailed account of work done, nature and quantity of materials used, and results obtained.													
Spotted 25 sack cement at bottom of hole. Pulled 1400 feet of 7" casing. Kan 15 sack of cement plug on top of casing stub at 1400 feet. Ran 15 sach of cement plug at bottom of 8 5/8" casing. Put bull plug in top of 3 5/3 " casing. Belle McCord will make water well out of this hole. RECEIVED													
FEB 2.6 1582													
) TRA	T. C	, C.	
Witnessed by	Witnessed by					Position			Company				
Nola-	Nola Carder FILL IN BELOW FOR REMED							Martin Yates, III					
						NAL W							
DF Elev.		TD			PBTD	1			Producing	Interval	Con	pletion Date	
Tubing Diam	eter	Tubing Depth		Oil Stri			ng Diame	Diameter Oil		il String Depth			
Perforated In	terval(s)					I						<u> </u>	
Open Hole In	Open Hole Interval							Producing Formation(s)					
RESULTS OF WORKOVER													
Test	Date of Test		Oil Production BPD			Gas Production MCFPD		Water Production BPD		GOR Cubic feet/Bbl		Gas Well Potential MCFPD	
Before Workover													
After Workover													
							I hereby certify that the information given above is true and complete to the best of my knowledge.						
Approved by Howard E. Lobley							Name Mola Curda						
合理、思想所 原石材 计约约时时行分析段							Position						
MAR 2 1962							Company						