



☐

CALIPER SURVEY.....☐

TEMPERATURE SURVEY.....☒

COMPANYMartin Yates 111LEASE McCordWELL No. 1FIELD WC

COUNTY EddySTATE New Mexico

LOCATIONELEVATION

OWNER'S REPRESENTATIVE

RECORDED BY SpidellUNIT No. 6001

| WELL DATA             |         | SURVEY DATA                                         |  |
|-----------------------|---------|-----------------------------------------------------|--|
| ZERO POINT Floor      |         | ZERO POINT Floor                                    |  |
| 7" CASING FROM 0      | TO 1883 | DATE 9/13/52                                        |  |
| CASING FROM           | TO      | HOURS AFTER CEMENTING 12                            |  |
| CASING FROM           | TO      | FOOTAGE LOGGED 650                                  |  |
| OPEN HOLE INCHES FROM | TO      | DEPTH OF SURVEY 650                                 |  |
| OPEN HOLE INCHES FROM | TO      | PURPOSE OF SURVEY Locate top of cement              |  |
| OPEN HOLE INCHES FROM | TO      |                                                     |  |
| BIT SIZE INCHES FROM  | TO      |                                                     |  |
| BIT SIZE INCHES FROM  | TO      |                                                     |  |
| TOTAL DEPTH           |         | RESULTS OF SURVEY                                   |  |
| OTHER INFORMATION     |         | Located top of cement approximately 255' below zero |  |
|                       |         | 225 sax 8% gel                                      |  |
|                       |         | 75 sax neat                                         |  |
|                       |         |                                                     |  |
|                       |         |                                                     |  |
|                       |         |                                                     |  |
|                       |         |                                                     |  |

