

Form 9-237a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office AlbuquerqueLease No. LC 065346

Unit _____

RECEIVED

MAR 9 1960

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 15, 1959

Well No. 1 Lee- Federal is located 130 ft. from (N) line and 130 ft. from (E) line of sec. 17

NE 17 T4S., R6E. RMP

($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat Sddy New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3352 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

In accordance with instructions from the U.S. and State Engineer well was plugged abandoned as follows:

1. Representative of state engineer's office witnessed plugging.
2. Pumped cement plug below and into 7" casing, cut 7" casing at 1250', and pumped 110 sack cement plug at 1200'.
3. Set ten sack cement plug in surface hole, leveled location, and set surface marker.

Location ready for final inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company E. P. CampbellAddress 7114 Central StAlbuquerque, New MexicoBy Ben RanganTitle Geologist