

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Field Office

Lease No. 09392

Unit D

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Key 24

194

Well No. 1-B is located 330 ft. from [N] line and 530 ft. from [E] line of sec. 4, 34
243 262 N40°E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Black River Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Hole filled with mud laden fluid, 7" casing picked 60' off bottom, cement plug placed from P.D. to 1950. Pulled all 7" casing. Pulled 8 5/8" casing. Placed cement plug from 250' to 200' (25 sax). Pulled 10 3/4" casing. Filled hole and placed cement cap at bottom of cellar (8 sax). Cleared location and levelled pit and cellar.

RECEIVED
JUN 1 1954
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Loda Oil Company

Address Post Office Box 536

McCombs Texas

By

Title Superintendent