

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

C RISP, NEW, MEXICO, April, 11, 1939

Place

Date

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

DUPLICATE

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the

E. Paul Moran, Crawford Smith

Well No. _____ in the

NW 1/4 Sec. 26 E

Lease S

26 E

Black River

of Sec.

Eddy

T.

R.

N. M. P. M.,

Field,

August, 10, to 28th, 1938

County.

The dates of this work were as follows:

Notice of intention to do the work was (was not) submitted on Form C-102 on _____ 19____

and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

10 sack cement set at 2000'. Hole was then mudded to 1630' which is the base of the bottom salt. Here ten sack more cement was set, then mud again to 1280' which is the base of the top or first salt. Ten more sack cement were used here, and then hole was filled with mud to 100' feet below surface of ground. 10 sack cement was used here and remainder of hole was left open to be used as a water well on this farm. (Crawford Smith). Five sack cement were also set at 1070' which is the top of salt.

E. Paul Moran

Owner

Witnessed by _____

Name

Company

Title

Subscribed and sworn before me this 13th

day of April, 1939

I hereby swear or affirm that the information given above is true and correct.

Name E. Paul Moran

Position Owner

Representing Self.

Company or Operator

My commission expires August 5, 1941

Address _____

Remarks:

Hole was tested for water after each run of cement was made and never showed any water after 10 sx. cement was set on bottom.

OIL & GAS INSPECTOR

Title