			\rightarrow \sim		,						
I NUMBER OF C	OPIES RECEIVED						й 	,			
	DISTRIBUTION										
SANTA FE NEW MEXICO OIL CONSER							ON COMM	ISSION	FORM C-103		
I	LAND OFFICE (Rev 3-55)										
PRORATION OFFICE (Submit to appropriate District Office as per Commission Rule 1106)											
Name of Cor					Addr						
J. Gle	nn Bennett	: Esta			and the second se	Box 953,	Midland,	EDET	NED		
Lease Bra				Well No. Unit	Range 1						
Date Work P	erformed 1-4-61		Pool Cass-Dr	w Del	ur	20 County	Eddy	Mna -	- -		
			THIS IS	A REPORT OF:	(Checl	k appropriate bloc	k)	0.6	DEFICE		
THIS IS A REPORT OF: (Check appropriate block) D. B. J. B. J. D. F. C. D. F. C. D.											
Plugging Remedial Work											
Detailed acc	count of work d	lone, nat	ure and quantity o	of materials used,	and re	sults obtained.					
1384 f	eet & 10 s	ax @ :		pipe left :					et; 25 sax @ location		
				660	12						
Witnessed by	Witnessed by Posit					Company					
			FILL IN BEL	OW FOR REME			S ONLY				
ORIGINAL WELL DATA											
				PBTD			Producing Interval		ompletion Date		
Tubing Diam	eter	נן	ubing Depth		Oil Stri	ing Diameter	0	il String Dep	oth		
Perforated In	terval(s)		<u></u>			<u> </u>		······			
Open Hole In	Dpen Hole Interval						Producing Formation(s)				
				RESULTS OF	WOR	KOVER					
Test	Date of Test		Oil Production BPD	Gas Product MCFPD		Water Production BPD		GOR feet/Bbl	Gas Well Potential MCFPD		
Before Workover											
After Workover											
							I hereby certify that the information given above is true and complete to the best of my knowledge.				
Approved by U. a. Gressett						Name FG Brichumidgi					
						Position Attended to the the					
						Company Roman Fotod					
						J. Glenn Bennett Estate					