

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Cabeen Exploration Corporation				Address Room 1502, 211 N. Ervay, Dallas 1, Texas			
Lease Crawford	Well No. 1	Unit Letter K	Section 9	Township 24S	Range 27E		
Date Work Performed		Pool Wildcat		County Eddy			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☒ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Spotted 25 sack plug across perforations @ 2169-2174 feet.
 Pulled approximately 1900 feet of 4½" casing.
 Spotted 25 sack plugs between 1558-1645 feet, @ 1270 feet & @ 400 feet.
 Spotted 10 sack plug in top of surface pipe, with surface marker.
 Mud was placed between all plugs.
 The surface was cleared and levelled.

RECEIVED

MAR 1962

O. D. C.
ANTHONY, OFFICE

Witnessed by	Position Oil & Gas Inspector	Company New Mexico Conservation Commission
--------------	--	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval			Producing Formation(s)	

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by *Howard E. Lohley*Name *Tom Boyd, Jr.*Title
*Oil and Gas Inspector*Position
Production ManagerDate **MAR 8 1962**Company
Cabeen Exploration Corporation

[illegible]