


JUN 22 1949

APPROVED

Frank B. Stand
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas June 16, 1949

Well No. 1 located 1980 ft. from [N] line and 1980 ft. from [E] line of sec. 31

SW/4 of NE/4 of Sec. 31 24-S 27-E
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Black River Wildcat Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3460 ft.

DETAILS OF WORK

(State nature of and expected depths to objective sands; show size, weights, and lengths of proposed casings; indicate reworking jobs, cementing points, and all other important proposed work)

Tested 9-5/8" casing with 1000# for 30 minutes at 3:30 AM 6-15-49. Tested O.K.
Tested perforations at 2785' with 1200# for 30 minutes at 8:00 PM 6-15-49.
Tested O.K.

U. S. GEOLOGICAL SURVEY
RECEIVED
JUN 21 1949

ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before it may be commenced.

Company Humble Oil & Refining Company

Address Box 1600
Midland, Texas

By *J. F. Ruskman*
Title Asst. Division Superintendent

FE4