



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **LC 042679**
Unit **K**

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **1** is located **1900** ft. from **S** line and **1900** ft. from **W** line of sec. **9**
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
23-S **20-E**
(Field) (County or Subdivision) (State or Territory)
New Mexico

The elevation of the derrick floor above sea level is **3034** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.S. 2400 - The following cement plugs were spotted: 1000'-1008, 1070'-1078', 1044'-1044'. Erected a monument, screwed into a coupling on top of the surface casing in accordance with instructions. Job was completed July 4, 1960

RECEIVED

JUL 12 1960

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operation.

Company **Harry D. Kuhn**
Address **P. O. Box 920**
Del Rio, Texas

By **Harry D. Kuhn**
Title **Operator**