

OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

Miscellaneous Reports on Wells

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

May 26, 1952

Date

Midland, Texas

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the.....

Southern California Petroleum Corp. **Landrum** Well No. **2** in the
Company or Operator Lease

SE/4 SE/4 of Sec. **12**, T **24-S**, R **28-E**, N. M. P. M.,

Malaga (Ext.) Field **Eddy** County.

The dates of this work were as follows:.....

Notice of intention to do the work was ~~accepted~~ submitted on Form C-102 on **4/28 and 5/21** 19**52**
and approval of the proposed plan was ~~secured~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Cemented 5½" casing at 2736' with 200 sax at shoe and 100 sax through 2-stage tool at 1005'. WOC 48 hours. Drilled out cement at 2-stage tool, bail tested, water not shut off. Perforated 4 holes at 1090', squeezed with 100 sax. WOC 48 hours. Water shut-off no good. Shot 4 holes 998, squeezed with 100 sax, WOC 48 hours. Water shut-off no good. Squeezed with 100 sax, WOC 36 hours, Water shut-off no good. Squeezed with 110 sax, put 8 sax away and pressure built up to 2800#. Found hard cement, drilled out cement 58 feet to 1110'. Water shut-off OK. Drilled out shoe at 2736', bail tested 1 hour, water shut-off OK.

Witnessed by **A. T. Mannon, Jr.** **Southern California Petroleum Corp.**
Name Company Title

Subscribed and sworn before me this **26th**

I hereby swear or affirm that the information given above is true and correct.

day of **May**, 19**52**

Name **Paul H. Hanger**

Position **Division Geologist**

Representing **Southern California Petroleum Corp.**
Company or Operator

My commission expires **June 1, 1953**

Address **P. O. Box 172, Midland, Texas.**

Remarks:

L. A. Hancock
Name

Title