NEW MEXICO OIL CONSERVATION DI 811 S. First Street ARTESIA, NEW MEXICO 88210

MOIF

	Ph (505) 748-1283	DATE 1/27/99	
Calvin & Alma Tennisc	on		
2401 Martin Lane			
Carlsbad, NM 88220		Re: Plugging Reports	
Gentlemen:			
Form C-1.03 Report of 1	Plugging for your <u>Malaga Ut</u> Lease	Well No. Ut. S-T-R	
of the location and for	bund it to be cleared to ∞	etive has made an inspection uply with Division Rules and upprovided to indicate that the	
(,) 1. All pits ha	we been filled and leveled.		
` '	l cellar have been filled and		
level has be section or u have been pe	A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, township and range numbers which have been permanently stenciled or welded on the marker.		
() 4. The location ground conto	location has been leveled as nearly as possible to original top and contour and has been cleared of all junk and equipment.		
() 5. The dead men	and tie downs have been cut	and removed.	
() 6. If a one well burn pit loca	l lease or last remaining we ations have been leveled and	ell on lease, the battery and cleared of all junk & equipment.	
The above are minimum relocations for plugged a	requirements and no plugging and abandoned wells have bee	pond will be cancelled until all in inspected and Form C-103 approved.	
in the blank form below	atlined above has been done, and returning this letter one than one trip to the lo	please notify this office by filling to us so that our representative cation.	
1122 1100 1100			
	Mi	niko Swikhiolo ike Stubblefield eputy Oil & Gas Inspector	
FILL IN BELOW AND RETURN I certify that the above for your inspection and	—. e work has been done and the	e above mentioned lease is ready	
	_	AME TO SERVICE THE PROPERTY OF	

TITLE