

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
RECEIVED P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

SEP - 5 '89

O. C. D.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well	7. Unit Agreement Name Malaga Unit
2. Name of Operator The Eastland Oil Company	8. Farm or Lease Name Tr - 4
3. Address of Operator P. O. Drawer 3488, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> , <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>24S</u> RANGE <u>28E</u> N.M.P.M.	10. Field and Pool, or Wildcat Malaga Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 2963 GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Repair leak on casing	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mechanical Integrity Test on 8/24/89 Tr 4 - #1 did not hold required pressure.
8/31/89 dug out around well and found to be leaking in weld on Bell Nipple on 5 1/2" csg.
just below ground level. Plans are to reweld and retest. You will be notified 24 hrs
before work to be done.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lewis Reed TITLE Production Superintendent DATE September 1, 1989

APPROVED BY Johnny P. Brown TITLE Oil and Gas Inspector DATE 9-28-89