



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe, N.M.Lease No. NM 087

Unit _____

RECEIVED

OCT 24 1960

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. C.

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	ARTESIA, OFFICE
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

30-015-02507

May 22

1959

Todhunter Federal

Well No. 1 is located 1980 ft. from {N} line and 660 ft. from {E} line of sec. 27C SW/4NW/4, Sec. 27
(1/4 Sec. and Sec. No.)24-S
(Twp.)28-E
(Range)N.M.P.M.
(Meridian)Wildcat

(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3006 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

271' of 7" surface was left in the hole intact. Cement plugs were circulated in, and heavy mud between, as follows:

- 10 sacks @ 2650' (total depth)
- 10 sacks @ 2311' (base of salt)
- 10 sacks @ 271' (base of surf. casing)
- 10 sacks @ surf.

A regulation marker was erected and the surface cleaned up. The New Mexico Engineers office witnessed the plugging.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ernest A. Hanson & S. D. DenisonAddress P. O. Box 852Roswell, New MexicoBy Harry E. HansonTitle Geologist, E. A. Hanson