

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 070116-A

Unit _____

RECEIVED
SEP 15 1952
CIVIL COMM.
Artesia Office

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL <input checked="" type="checkbox"/>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

9-8, 19 52

Federal Hall

Well No. 1 is located 330 ft. from N line and 2310 ft. from E line of sec. 6

3W/4 Sec. 6 24-S 29-E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Malaga Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2982 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was drilled to TD 2820' without encountering oil or gas in any commercial quantities. Swabbed 1 1/2 bbls. fluid per hr., 3 gals oil & rest salt water at TD 2820'.
We desire to plug & abandon well as follows:

(SEE OVER)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tennessee Production Co.

Address Box 1031
Midland, Texas

By E. H. Huxford
Title Vice President

1. Circulate hole w/Heavy Mud.
2. Spot Cement plugs as follows:
 - 6 sx - 2735-2820
 - 16 sx - 850-900
 - 10 sx - 280-310
 - 5 sx - at surface
3. Level & clear location & cement in 4" x 4' marker.