

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 070116-A
Unit _____

30-015-03694
SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal Hall
Well No. 1 is located 330 ft. from N line and 2310 ft. from E line of sec. 6
34/4 Sec. 6 24-S 29-E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Malaga Ady New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2954 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Since well has been drilled to TD 2820' without showing for oil or gas in commercial quantities it was plugged & Abandoned as follows:

(see over)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tennessee Production Co.

Address Box 1031

Midland, Texas

By E. L. Murrell
Title Vice President

cc: NWCCC

1. Circulated hole w/heavy mud.
2. Spotted following cement plugs
 - 10 sx 2735-2820
 - 16 sx 850-900
 - 10 sx 285-310 (bottom 8 5/8" csg. set @ 305')
 - 5 sx at surface
3. Set 4" x 4' marker above surface & cleaned up location.
Completed plugging & Abandoning 10-4-52.