


Land Office **Las Cruces**Lease No. **069511**

Unit _____

RECEIVED**APR 13 1962**

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**SUNDRY NOTICES AND REPORTS ON WELLS****D. C. C.**
ARTESIA OFFICE

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 6, 1962

Well No. **3** is located **660** ft. from **[N]** line and **1980** ft. from **[E]** line of sec. **33****NW/4 of NE/4 Sec. 33**
(1/4 Sec. and Sec. No.)**23-S**
(Twp.)**31-E**
(Range)**N.M.P.M.**
(Meridian)**Wildcat**
(Field)**Eddy County**
(County or Subdivision)**New Mexico**
(State or Territory)The elevation of the derrick floor above sea level is **3406** ft.**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs; cementing points, and all other important proposed work)

Well was drilled to total depth of 4358' without encountering any shows of oil and/or gas, then plugged and abandoned as per U.S.G.S. instructions.

1st Plug	22 Sacks	T.D. to 4240'
2nd Plug	19 Sacks	2760' to 2660'
3rd Plug	20 Sacks	850' to 750'
4th Plug	4 Sacks	20' to 0'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **PATOLL CORPORATION**Address **605 Midland National Bank Building****Midland, Texas**By **O. H. Stanfield**
Title **Production Superintendent**