

(SUBMIT IN TRIPLICATE)

DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	
Lease No ICon.	85346
Unit	E
ر)	· · · · · · · · · · · · · · · · · · ·

GEOLOG	ICAL SURVEY					
SUNDRY NOTICES AND REPORTS ON WELLS						
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDONMENT. SUPPLEMENTARY WELL HISTORY.					

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

ימינ		Hotels, 1	ion Mexico	Feb. 15	, 19 61
Well No is located	1980 ft. fr	om. $\left\{S\right\}$ line an	d . 1980 ft. fron	$n\left\{ egin{array}{c} E \\ \bullet \end{array} ight\}$ line of sec	18
(% Sec. and Sec. No.)	2 4S	(Range)	Zố E (Meridian)		
	(Coun	y or Subdivision)		taxico tate or Territory)	-
The elevation of the derrick flo	or above sea	level is 3734	ft.		

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is proposed to drill to approximately 12,100° to evaluate Morrow Sand.

NUTICE OF INTENTION TO DRIVE APPROVED 9-16-60.



FEB 1 6 1961

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company Oulf (11) Corporation				
Address P. D. Ben 2167	Joriginal Signed By			
Hobbs, Hen Mexico	By			
	Title Area Production Manager			