

Details of bop test

H N G Oil Company


Pardue #1

3/13/74


Contractor: Moran Drlg. Rig 8

Test by Yellow Jacket Tools and Services, Inc.

=====Transposition of the pressure recorder charts=====



=====Transposition of the pressure recorder charts=====



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Carlsbad, New Mexico Area, Midland District, Texas. Test was made with test plug landed in casing head with the following test results:

Arrived location - crew changing out kelly.