


Morris R. Antweil - #1 Missouri-New Mexico Land Company Wildcat, 1980' PEL,
990' FSL, Sec. 6, T-23-S, R-27-E, Eddy County, New Mexico

Following is a summary of slope tests taken with the best instruments
available on the above captioned well. These tests indicate inclination from vertical.

<u>Depth in Feet</u>	<u>Deviation in Degrees</u>
325	3/4
659	3/4
1124	5-1/4
1218	5-1/4
1289	4-3/4
1352	4-3/4
1415	4-3/4
1509	4
1626	4-3/4
1721	4-1/4
1765	3-3/4
1830	3
2034	3
2283	1-3/4
2414	2-1/4
2600	1
2850	3/4
3030	1
3387	1/2
3807	3/4
4017	1/2
4408	3/4
4624	3/4
4971	3/4
5360	1-1/4
5852	1/4
6304	3/4
6605	3/4
6916	3/4
7362	1-1/2
7677	1-1/2
8115	1-1/2
8530	1-1/4
8913	1-1/2
9367	1-3/4
9697	1-3/4
9744	1-1/2
9966	1-1/2
10264	1-3/4
10320	1-3/4
10440	1-3/4
10731	1-3/4
10812	1-1/4
11110	1-1/2
11660 TD Driller	1-3/4

RECEIVED


D.C.G.
ARTESIA, OFFICE


Dorman D. Graves, Division Geologist
DELTA DRILLING COMPANY

STATE OF TEXAS I

COUNTY OF ECTOR I

The foregoing instrument was acknowledged before me this 31st day of March, 1970, by
Dorman D. Graves, known to me to be the person whose name is subscribed hereto, who, after
being duly sworn, on oath states that the above is true and correct to the best of his knowledge.


Lynna Jo Edwards, Notary Public in and for
Ector County, Texas