

LEASE NAME & NO. J. R. Joyce #1  
NAME OF OPERATOR: Caroline Hunt Sands  
ADDRESS OF OPERATOR: Drawer 1350, Midland, Texas 79701  
LOCATION OF WELL: Unit D, 990' from North line & 990' from West  
line of Sec. 28, T-23-S, R-23-E, Eddy County,  
New Mexico.  
FIELD NAME: Wildcat

SUMMARY OF DRILL STEM TESTS:

DST #1: 8300-8430'. Opened with good blow and continued throughout test. Recovered 40' drilling mud. IFP (10 mins) 43#, ISIP (1 hour) 276#, FFP (2 hours) 43#, FSIP (1 hour) 257#, IHP 3957#, FHP 3937#.

DST #2: 10,440-10,550'. Tool open with good blow for 20 minutes and weak blow for balance of 1 hour test. Recovered 7780' salty sulphur water. IHP 4985#, IFP (10 mins) 435#, ISIP (1 hour) 4214#, FFP 3456#, FSIP (1 hour) 4201#, FHP 4985#.