

YATES PETROLEUM CORPORATION
Ed Wood ASE Federal #1
Section 12-T24S-R23E
Eddy County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 10390-10422': TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 60". RECOVERY:
971' of mud. SAMPLER: 0 CFG & 2600 cc mud. PRESSURES: IHP 5129; IFP 91-80;
ISIP 382; 2nd FP 130-145; 2nd SIP 5127; 3rd FP 338-382; BHP 5123

DST #2 10380-10495' - Misrun

DST #3 10462-10495' (Morrow): TIMES: 20"; SI 60"; TO 60"; SI 120"; TO 90".
RECOVERY: 2053' of gas cut mud. SAMPLER: 5.97 cfg and 100 cc mud. PRESSURES:
IHP 5272; IFP 284-380; ISIP 788; 2nd FP 380-414; 2nd SIP 3713; 3rd FP 578-788;
FHP 5272