

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.
NM 040547

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Gulf Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
South Carlsbad Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 1, T-23-S, R-26-E

12. COUNTY OR PARISH
Eddy

13. STATE
N. M.

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Pennzoil Company

OCT 11 1972

3. ADDRESS OF OPERATOR

P. O. Drawer 1828 - Midland, Texas, O. C. G. ARTERIA/ OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980 FSL & 1980 FWL of Section 1, T-23-S, R-26-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-7-72 Perforated w/2 jet shots per foot w/thru tubing gun @ following intervals:

11,693', 697', 702', 704', 750', 754', 857', 859', 861',
11,863', 865', 866' (Total 15' & 29 holes)

Flwd. to pits for 2 hours to clean up.
Turned thru separator to gauge. - Prep to run 4-point

9-21-72 Ran Multipoint Back Pressure Test (Data attached)

RECEIVED

OCT-4 1972

U. S. GEOLOGICAL SURVEY
ARTERIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Petroleum Engineer

DATE 10-3-72

(This space for Federal or State office use)

APPROVED BY
CONDITION OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
OCT 10 1972

L. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side