## Morris R. Antweil

OIL OPERATOR P. O. Box 2010 Hobbs, New Mexico 88240

October 9, 1974

RECEIVED

0011 101

New Mexico Oil Conservation Commission Post Office Drawer "DD" Artesia. New Mexico 88210

D. C. M.

Attention: Mr. W. A. Gressett

Gentlemen:

Be: Artweil No. 1 Allen J-31-T22S-R27F South Carlsbad Gas Pool Eddy County, New Mexico

Enclosed, is a C-103 reporting our repair of a tubing leak in captioned dual completion and the subsequent acid treatment of the Morrow interval. The tubing leak was detected by the presence of Strawn condensate in the Morrow production stream. Immediate action was taken to locate and repair the leak.

The Morrow interval is producing about 1.5 WMCFPD following treatment: while the Strawn interval is cleaning up slowly from the approximate 1,200 barrels of KCL-treated water which was lost to the interval while pulling, testing, and re-running the tubing strings.

The shut-in tubing pressure measurements and packer leakage tests which should have been taken on the captioned well during September will be run and reported as soon as the production from the Strawn interval stablizes.

Yours very truly,

MORRIS R. ANTYEIL

R'm William

8. M. Williams

RMW/lh

Enclosures (4)