

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

NEW MEXICO OIL & GAS COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

FE 6 1973

|                                |   |
|--------------------------------|---|
| 5a. Indicate Type of Lease     |   |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |   |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|  |   |
|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>   | 7. Unit Agreement Name                                      |
| 2. Name of Operator<br><b>Cities Service Oil Company</b>   | 8. Farm or Lease Name<br><b>Spencer A</b>                   |
| 3. Address of Operator<br><b>Box 4906 - Midland, Texas 79701</b>   | 9. Well No.<br><b>1</b>                                     |
| 4. Location of Well<br>UNIT LETTER <b>0</b> , <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>30</b> , TOWNSHIP <b>22S</b> , RANGE <b>27E</b> , N.M.P.M. | 10. Field and Pool, or Wildcat<br><b>S. Carlsbad Strawn</b> |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br><b>3184' GR.</b>  | 12. County<br><b>Eddy</b>                                   |

|  |  |
|--|--|
| 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data |  |
| NOTICE OF INTENTION TO:  | SUBSEQUENT REPORT OF:  |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                               | REMEDIAL WORK <input type="checkbox"/>   |
| TEMPORARILY ABANDON <input type="checkbox"/>                                 | COMMENCE DRILLING OPNS. <input type="checkbox"/>                               |
| PULL OR ALTER CASING <input type="checkbox"/>                                | CASING TEST AND CEMENT JOB <input type="checkbox"/>                            |
| OTHER <input type="checkbox"/>   | OTHER <b>Retesting of SI Zone (Strawn)</b> <input checked="" type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**T.D. 11,820' Shale, P.B.T.D. 11,764'. Testing complete. The Strawn zone (perfs. 10,413-10,429) was retested during the first part of June, 1972 with following results:**

**Flowed 2.405 MMCF + 8 B dist. + 13.9 BW/8 hrs. thru 8/64" choke, flowed 1.052 MMCF + 23.6 B dist. + 8.3 BW/11 hrs. thru 10/64" & 1" chokes, flowed 600 MCF + 12.47 B dist. + 1.34 BW/4 hrs. thru 20/64" choke, flowed 524 MCF + 11.08 B dist. + 1.38 BW/4 hrs. thru 20/64" choke and flowed 521 MCF + 13.89 B dist./3-1/2 hrs. thru 20/64" choke. Test results indicate the Strawn zone to be commercial by producing the well on intermittent basis. This zone was connected by LLano, Inc. on 1-25-73 and by Transwestern on 1-26-73.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. J. Judd TITLE Region Operation Manager DATE January 31, 1973

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE FEB 6 1973

CONDITIONS OF APPROVAL, IF ANY: