

Morris R. Antweil - Randall No. 1, 1864 FSL, 2005 FWL, Section 21, T-22-S, R-27-E,
Eddy County, New Mexico

Following is a summary of slope tests taken with the best instruments available on the
above captioned well. These tests indicate inclination from vertical.

<u>Depth</u>	<u>Angle of Inclination (degrees)</u>
147	1/2
374	3/4
575	1
740	1
1,070	1-1/4
1,200	1-1/4
1,320	1
1,440	1
1,662	3-1/4
1,694	3-3/4
1,730	3-1/4
1,760	3-1/2
1,790	3
1,820	3-1/2
1,859	3-3/4
1,880	3-1/2
1,922	3-3/4
1,950	3-3/4
1,980	3-1/2
2,010	3-1/4
2,045	3
2,076	3-3/4
2,147	3
2,209	3-1/4
2,330	3-1/4
2,450	3
2,510	2-3/4
2,638	2-3/4
2,760	2-3/4
2,877	3
3,030	2-1/4
3,150	2-1/2
3,322	2
3,568	1-3/4
4,040	1
4,380	1/2
4,870	1/2
5,370	1/2
5,445	1/2
5,879	3/4
6,370	1/4
6,926	3/4
7,326	3/4
7,700	3/4
8,200	3/4
8,610	1-1/2
9,110	1-1/2
9,560	1-1/2
10,010	1-1/2
10,447	1-1/2
10,705	1/2
10,995	1-3/4
11,155	1/2

RECEIVED

AUG 8 1972

O. C. C.
ARTESIA, OFFICE